

S.G. CIRCULAR NO. 8/1954

Fire Precautions

What might have turned out to be a serious fire in this 11 cadquaters yesterday was put out by prompt action and the availability of fire – fighting appliances in full working order on the premises.

2. Chief Surveyors are asked to inspect oll the offices under their control and satisfy themselves that the exiting fire precautions are adequate. This involves the handy location of fire extinguishers and red – pointed buckets of fresh water and sand. Where smoking is permitted ash trays should be provided and any officer dropping a cigarette butt on a wooden floor should be disciplined.

3. As and added precaution the local fire services officer should be invited to inspect and advise.

C.NOBLE
Surveyor General,
Malaya.

Dated: 30 October, 1954.